

<b>8.</b>	<b>Investigation of Installed Timber Piles.....</b>	<b>101</b>
8.1	Experimental Design.....	101
8.1.1	In-situ Testing.....	102
8.1.2	Extracted-wet Testing.....	102
8.1.3	Extracted-dry Testing.....	104
8.1.3.1	Kiln Drying.....	105
8.2	Cutting of Pile Sections.....	108
8.3	Determination of Remaining Cross-sectional Area.....	109
8.4	Test Results.....	113
8.4.1	Frequency Information.....	114
8.4.2	Phase Velocity Information.....	117
8.4.2.1	Impact Device.....	117
8.4.2.2	Selection of Standard Kernel.....	118
8.4.2.3	In-situ Results.....	119
8.4.2.4	Extracted-wet Results.....	119
8.4.2.5	Extracted-dry Results.....	119
8.4.2.6	Effect of Boundary Conditions.....	121
8.4.2.7	Number of Lines and Data Files to be Considered for Each Test Location.....	123
8.4.2.8	Relationship between Phase Velocity and Liquid Content.....	125
8.4.2.9	Formation of Condition Analysis Charts.....	128
<b>9.</b>	<b>Conclusions.....</b>	<b>136</b>
	<b>List of References.....</b>	<b>139</b>